

Table of Contents

Version 1.4.1 (V1.4.1_210511)	1
Release	1
Bug Fixes	1

Version 1.4.1 (V1.4.1_210511)

Release

2021-06-01

Bug Fixes

1. Card data were output with the wrong BitCount while the device was communicating with a 3rd party controller via OSDP. (Affects version: v1.0.0)
2. While the device was communicating with a 3rd party controller via OSDP, the device connected as a slave responded that it supported transparent mode by OSDP_PDCAP even though it did not actually support that mode. (Affects version: v.1.0.0)
3. It was not able to communicate with a 3rd-party controller via OSDP with the default key before network initialization. (only for devices released with the firmware version 1.4.0 or later) (Affects version: v1.4.0)
4. It was able to communicate using default keys after changing the key settings when the device was connected to a 3rd-party device via OSDP. (Affects version: v1.3.0)
5. After initializing the slave device's settings, it was not able to connect it to a 3rd-party controller. (Affects version: v1.0.0)
6. Secure communication was not available by using the default key after downgrading firmware to version 1.3.1 or below which does not support encryption. (Affects version: v1.4.0)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:ber2_revision_note_141

Last update: **2021/06/01 13:04**