# **Table of Contents**

| /ersion 1.4.1 (V1.4.1_210412) | 1 |
|-------------------------------|---|
| Release                       | 1 |
| New Features and Improvements | 1 |
| Bug Fixes                     | 1 |

# Version 1.4.1 (V1.4.1\_210412)

#### Release

2021-04-12

### **New Features and Improvements**

- 1. Upgraded to the 1.1.1i version of OpenSSL.
- 2. Intelligent Slave Support
- Intelligent Slave: A function that enables 1:1 or 1:N matching directly from the Suprema device and transmits the authentication result as OSDP card data to the third-party controller.
- 3. Separated event logs of Mobile Access cards and RFID cards.

## **Bug Fixes**

- 1. When calling the BS2\_ResetConfigExceptNetInfo API from the BioStar 2 Device SDK, a 'Timeout' error occurred. (Affects version: v1.0.0)
- 2. Card data were output with the wrong BitCount while the device was communicating with a 3rd party controller via OSDP. (Affects version: v1.0.0)
- 3. When using a static IP while DNS server address was configured, a reboot on the device caused communication problems between the server. (Affects version: v1.0.0)
- 4. While the device was communicating with a 3rd party controller via OSDP, the device connected as a slave responded that it supported transparent mode by OSDP\_PDCAP even though it did not actually support that mode. (Affects version: v1.0.0)
- **5**. If 31 slave devices were connected and one of the devices got disconnected, the master device rebooted. (Affects version: v1.0.0)
- **6.** Fingerprint authentication did not work after downgrading from firmware version 1.4.0 to firmware version 1.2.1. (Affects version: v1.4.0)
- 7. It was not able to communicate with a 3rd-party controller via OSDP with the default key before network initialization. (only for devices released with the firmware version 1.4.0 or later) (Affects version: v1.0.0)
- 8. It was able to communicate using default keys after changing the key settings when the device was connected to a 3rd-party device via OSDP. (Affects version: v1.3.0)
- 9. After initializing the slave device's settings, it was not able to connect it to a 3rd-party controller.

(Affects version: v1.0.0)

From:

http://kb.supremainc.com/knowledge/ -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bep2\_revision\_note\_141&rev=1622503024

Last update: 2021/06/01 08:17