Table of Contents

Version 1.1.1 (V1.1.1_240319)

Release

2024-03-20

New Features and Improvements

1. Improved pop-up message displayed when searching with unenrolled information in the **Search User** feature.

2. Improved pop-up message displayed when **Timed Anti PassBack** occurs.

3. Improved duplicate fingerprint detection.

4. Improved fingerprint capture quality.

Bug Fixes

1. **Duress** fingerprint cannot be deleted when the user has two or fewer fingerprints, including **Duress** fingerprint stored in it. (Affects version: v1.0.0)

2. When there is no firmware file on the USB connected to the device, pressing the arrow keys/OK button continuously in the **File List** of **FW Upgrade** causes the device to restart. (Affects version: v1.0.0)

3. When network is repeatedly disconnected in an environment using a wireless network, RF card authentication will fail. (Affects version: v1.0.0)

4. The user ID stored as a 32-character string is truncated to only 31 characters in a specific event log. (Affects version: v1.0.0)

5. If the authentication message containing the user ID and Name exceeds a certain number of characters, the device will terminate abnormally. (Affects version: v1.0.0)

6. If the number of fingerprints stored in the device exceeds the 1:N maximum, the **Finger** in **User Usage** count is displayed abnormally. (Affects version: v1.0.0)

7. When using the BS2_GetDeviceCapabilities function in the SDK to get information supported by the

device, the CustomClassicPlus and CustomDesFireEV1 are displayed as False though the device supports custom smart cards. (Affects version: v1.1.0)

8. When **Relay** is set in the device menu, the door does not open when authenticating with a mobile card + fingerprint. (Affects version: v1.0.0)

From:
https://kb.supremainc.com/knowledge/ -

Permanent link:
https://kb.supremainc.com/knowledge/doku.php?id=en:bs2a_revision_note_111

Last update: **2024/04/03 11:46**