

Table of Contents

Version 1.2.1 (V1.2.1_190304)	1
Release	1
Bug Fix	1

Version 1.2.1 (V1.2.1_190304)

Release

2019-03-12

Bug Fix

1. The device intermittently recognizes the HID Prox card as an EM card.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bep2_revision_note_121

Last update: **2021/06/01 08:43**