

# Table of Contents

Version 1.3.1 (V1.3.1_190228) .....	1
Release .....	1
Bug Fixes .....	1

# Version 1.3.1 (V1.3.1\_190228)

## Release

2019-03-12

## Bug Fixes

1. The device intermittently recognizes the HID Prox card as an EM card.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:bew2\\_revision\\_note\\_131](http://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_131)

Last update: **2021/05/31 08:36**