

Table of Contents

Version 1.8.1 (V1.8.1_240508)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.8.1 (V1.8.1_240508)

Release

2024-05-09

Devices with the new SE processor cannot downgrade to a lower version after upgrading the firmware to v1.7.1 or later.
Devices with existing SE processor can be downgraded to a lower version.
For more information, check the serial number of the device and contact the Suprema.
(<https://supremainc.com>)

New Features and Improvements

1. Improved to get user update succeeded event log using the GetLogWithFilter function in the SDK.
2. Supports new device.
 - BioStation 2a (BS2A-ODPB, BS2A-OAPWB)
3. Improved to allow the use of **Secure Tamper** regardless of the **Device Hashkey Management** option.

Bug Fixes

1. When authenticating an iClass AoC card and a fingerprint simultaneously, the device restarts abnormally. (Affects version: v1.0.0)
2. The user ID stored as a 32-character string is truncated to only 31 characters in a specific event log. (Affects version: v1.0.0)
3. When a user with a 32-character user ID authenticates to the device while the device is not connected to the server, the authentication event log is not updated in BioStar 2 even after the device is reconnected to the server. (Affects version: v1.0.0)

4. After a firmware upgrade, authentication failure occurs with the previously used cards. (Affects version: v1.8.0)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_181

Last update: **2024/06/11 17:38**