

Table of Contents

Firmware Version 1.2.0 (Build No. 1.2.0_251014) 1

Release 1

New Features and Improvements 1

Bug Fixes 1

Firmware Version 1.2.0 (Build No. 1.2.0_251014)

Release

2025-10-21

- After upgrading the firmware to v1.2.0, it is not able to downgrade to an earlier version of the firmware.
- For more information, check the serial number of the device and contact the Suprema (<https://supremainc.com>).

New Features and Improvements

1. Supports the **Master Admin** setting, which grants full administrator privileges.
2. Reflects global cybersecurity standards and the latest security requirements.
3. Added identification code to support recognition of the latest cards.
 - DESFire EV3
4. Improved time synchronization behavior between server and devices.
5. Improved keypad UI when entering username or ID.

Bug Fixes

1. When using **Device → Server** mode, the server IP address is reset if the connection to the DHCP server fails. (Affects version: v1.0.0)
2. When a user with more than two cards enrolled attempts card authentication to the Wiegand output device, the ID of a card other than the authenticated card is output. (Affects version: v1.0.0)
3. Arm/Disarm actions did not operate correctly on specific Supervised Input port of the DM-20

connected as a slave. (Affects version: v1.0.0)

4. Each time the **Device Info** menu is opened, the **WiFi MAC** address is displayed differently. (Affects version: v1.1.0)

5. Wiegand format card data of 25 bits or less is not recognized. (Affects version: v1.0.0)

6. When multiple devices are connected to a third-party control panel, rebooting one device causes the RS-485 connections of the other devices to be disconnected. (Affects version: v1.1.0)

7. After a firmware upgrade, authentication failure occurs with the previously used cards. (Affects version: v1.1.0)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge./doku.php?id=en:bs2a_revision_note_120

Last update: **2025/10/27 16:32**