Table of Contents

Version 1.4.1 (V1.4.1_250929)	. 1
Release	. 1
Rua Fixes	. 1

Version 1.4.1 (V1.4.1_250929)

Release

2025-09-29

- If you are using a device with firmware version v1.4.0, you must upgrade to v1.4.1 before use.
 - As important security and stability improvements are included, using the latest version after the upgrade is mandatory.
- After upgrading the firmware to v1.4.0, it is not able to downgrade to an earlier version of the firmware
- For more information, check the serial number of the device and contact the Suprema (https://supremainc.com).

Bug Fixes

- 1. Fixed issue where unnecessary logs were getting logged. (Affects version: v1.4.0)
- 2. Applying device settings in BioStar 2 causes a logout due to a WLAN encryption problem. (Affects version: v1.4.0)

From:

https://kb.supremainc.com/knowledge/ -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bs3 revision note 141

Last update: 2025/10/01 16:01