

Table of Contents

Version 1.5.3 (V1.5.3_221026)	1
Release	1
New Features and Improvements	1
Bug Fix	1

Version 1.5.3 (V1.5.3_221026)

Release

2022-11-02

New Features and Improvements

1. XPass D2 new BLE (Bluetooth Low Energy) chip firmware(Build No. 1.7.0_220921) support.
 - The BLE chip parts of the hardware have been changed, and the firmware has been upgraded to be compatible with both the existing and new BLE chips.
2. Added relay deactivation option for exit button input.
 - Added the option to set the door open request log to occur but the relay not to operate when the exit button is pressed.
3. Separated the log related to door unlock.
 - Door Unlocked (Exit Button)
 - Door Unlocked (By Operator)
4. Improved Arm/Disarm state to be written directly to the device's memory so that the state persists even if power is lost.

Bug Fix

1. Slave devices connected to specific RS-485 ports not being searched. (Affects version: v.1.0.0)

From:
<http://kb.supremainc.com/knowledge/> -

Permanent link:
http://kb.supremainc.com/knowledge./doku.php?id=en:cs40_revision_note_153&rev=1667868092

Last update: **2022/11/08 09:41**