

# Table of Contents

Version 1.0.14 (V1.0.14_160111) .....	1
Release .....	1
Bug fixes .....	1

# Version 1.0.14 (V1.0.14\_160111)

## Release

2016-01-19

## Bug fixes

1. OSDP ID is changed to zero and communication is not possible if FW upgrade is performed when connecting to BioStation 2 or BioStation A2 as a slave device.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge/doku.php?id=en:dm20\\_revision\\_note\\_1014](https://kb.supremainc.com/knowledge/doku.php?id=en:dm20_revision_note_1014)

Last update: **2021/05/14 10:54**