

# Table of Contents

Version 1.3.1 (V1.3.1_200422) .....	1
Release .....	1
Bug Fixes .....	1

# Version 1.3.1 (V1.3.1\_200422)

## Release

2020-04-27

## Bug Fixes

1. Changed the firmware downgrade policy.
  - The kernel of the firmware before the touch panel is replaced has been changed not to downgrade.
2. Adjusted the brightness of the IR LED.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge/doku.php?id=en:fs2\\_revision\\_note\\_131](https://kb.supremainc.com/knowledge/doku.php?id=en:fs2_revision_note_131)

Last update: **2021/05/12 09:28**