

Table of Contents

Version 2.1.4 (V2.1.4_230810) 1

Release 1

New features and improvement 1

Bug Fixes 1

Version 2.1.4 (V2.1.4_230810)

Release

2023-08-11

For devices with the new SE processor, after upgrading the firmware to v2.1.0 or higher, you cannot downgrade to a lower version and downgrade the firmware customized in the lower version.

Devices with existing SE processor can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema (supremainc.com).

New features and improvement

1. Improved face anti-spoofing performance when **Fusion Matching** and **Fake Detection** are set to **Normal**.
2. Added **Power Line Frequency** option to prevent flicker based on the illuminance environment in which the device is installed.

Bug Fixes

1. When authenticating with a BLE mobile card running on iOS, authentication fails and the device restarts intermittently. (Affects version: v1.0.0)
2. Device freezes when firmware upgrade to BioStar 2 with more than 50,000 registered users on the device. (Affects version: v2.1.1)
3. Restart log is not logged in the device's **Event Log** when the master device is restarted. (Affects version: v2.1.1)
4. Device does not recognize certain MIFARE Classic cards. (Affects version: v1.0.0)
5. Device does not recognize certain HID iCLASS Seos cards. (Affects version: v1.0.0)
6. When the device with the working **Screen Saver** is not used for a long time, a black screen occurs and the device freezes. (Affects version: v1.0.0)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:fsf2_revision_note_214&rev=1701058910

Last update: **2023/11/27 13:21**