

Table of Contents

1.0.5 (V1.0.5)

1

Release

1

Bug Fixes

1

1.0.5 (V1.0.5)

Release

2021-05-06

Bug Fixes

1. An infrared image was not displayed when connecting the device to the thermal camera.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:release_note_105

Last update: **2021/05/11 09:36**