

# Table of Contents

Version 1.3.2 (V1.3.2_230116) .....	1
Release .....	1
New Features and Improvements .....	1
Bug Fixes .....	1

# Version 1.3.2 (V1.3.2\_230116)

## Release

2023-01-26

Devices with the new BLE chip cannot downgrade to a lower version after upgrading the firmware to v1.3.1 or higher.

Devices with existing BLE chips can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema (supremainc.com).

## New Features and Improvements

1. Separated the log related to the cause of the door unlock.
  - Door open request by exit button
  - Door open request by operator
2. Added relay deactivation option for exit button input.
  - Added the option to set the door open request log to occur but the relay not to operate when the exit button is pressed.

## Bug Fixes

1. Card types not checked to be used in smart card settings gets issued normally (Affects version: v1.0.0).
2. Event logs and real-time logs are not output due to corrupted log records (Affects version: v1.0.0).
3. Deleting all users included in an access group in BioStar 2 does not delete the access group from the device's user information (Affects version: v1.0.0).
4. Improved the structure to prevent authentication fail caused by broken database or cache memory (Affects version: v1.0.0).

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:xp2\\_revision\\_note\\_132](http://kb.supremainc.com/knowledge/doku.php?id=en:xp2_revision_note_132)

Last update: **2023/02/01 13:07**