

# Table of Contents

Version 1.0.3 (V1.0.3\_210705) ..... 1

Release ..... 1

Bug fixes ..... 1

## Version 1.0.3 (V1.0.3\_210705)

### Release

2021-07-12

### Bug fixes

1. It was able to configure the HID Prox card settings for devices (XS2-QDPB, XS2-DPB) that do not support the HID Prox card from the server. (Affects version: v1.0.0)
2. The QR/Barcode sensor did not work properly. (Affects version: v1.0.2)
3. The user ID was output differently from the registered user ID when authenticating a QR/Barcode set as a blacklist. (Affects version: v1.0.2)
4. The existing QR/Barcode authentication option settings were not maintained after restarting the device. (Affects version: v1.0.2)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:xs2\\_revision\\_note\\_103&rev=1626221273](http://kb.supremainc.com/knowledge/doku.php?id=en:xs2_revision_note_103&rev=1626221273)

Last update: **2021/07/14 09:07**