

Table of Contents

Version 1.2.1 (V1.2.1_230418) 1

Release 1

New features and improvement 1

Bug Fixes 1

Version 1.2.1 (V1.2.1_230418)

Release

2023-04-26

New features and improvement

1. Separated event code for QR authentication.
 2. Improved smartcard output byte order setting.
- When using Wiegand or OSDP output, it is improved to be affected by the smartcard output byte order even when the Wiegand output information is as the user ID.

Bug Fixes

1. If the door uses the slave device relay, the door does not open even if authentication succeeds (Affects version: v1.0.0).
2. Device restarts when camera QR authentication using a QR code with large data (Affects version: v1.2.0).
3. Door Locked event occurs when input signal gets detected while configured to Arm/Disarm by input signal (Affects version: v1.0.0).
4. Device does not recognize some HID iCLASS Seos cards (Affects version: v1.0.0).

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:xs2_revision_note_121&rev=1683089130

Last update: **2023/05/03 13:45**