

# Table of Contents

Version 1.4.4 (V1.4.4_220914) .....	1
Release .....	1
New features and improvements .....	1
Bug Fixes .....	1

# Version 1.4.4 (V1.4.4\_220914)

## Release

2022-09-14

BEP2-OA type of BioEntry P2 model support HID iCLASS card type through SE processor. For devices with the new SE processor, after upgrading the firmware to v1.4.4, you cannot downgrade to a lower version and downgrade the firmware customized in the lower version. Devices with existing SE processor can be downgraded to a lower version. For more information, check the serial number of the device and contact the Suprema (supremainc.com).

## New features and improvements

1. Supports the dual SE processor.

## Bug Fixes

1. Incorrect Bit Count and card data were output when the Suprema device was connected to a 3rd-party controller via OSDP and the CSN card was registered in Wiegand format and authenticated (Affects version: v1.4.3).
2. Device does not recognize some HID iCLASS Seos cards (Affects version: v1.0.0).
3. Event logs and real-time logs are not output due to corrupted log records (Affects version: v1.0.0).
4. Improved the structure to prevent authentication fail caused by broken database or cache memory (Affects version: v1.0.0).

From:  
<http://kb.supremainc.com/knowledge/> -

Permanent link:  
[http://kb.supremainc.com/knowledge./doku.php?id=en:bep2\\_revision\\_note\\_144&rev=1675233931](http://kb.supremainc.com/knowledge./doku.php?id=en:bep2_revision_note_144&rev=1675233931)

Last update: **2023/02/01 15:45**