

Table of Contents

Version 1.3.1 (V1.3.1_190228)	1
Release	1
Bug Fixes	1

Version 1.3.1 (V1.3.1_190228)

Release

2019-02-28

Bug Fixes

1. The device intermittently recognizes the HID Prox card as an EM card.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_131&rev=1622167678

Last update: **2021/05/28 11:07**