

# Table of Contents

Version 1.7.1 (V1.7.1_221220) .....	1
Release .....	1
New features and improvements .....	1
Bug Fixes .....	1

# Version 1.7.1 (V1.7.1\_221220)

## Release

2023-01-11

Devices with the new SE processor cannot downgrade to a lower version after upgrading the firmware to v1.7.1 or higher.  
Devices with existing SE processor can be downgraded to a lower version.  
For more information, check the serial number of the device and contact the Suprema (supremainc.com).

## New features and improvements

1. Supports a new SE processor and new firmware.
2. Separated the log related to door unlock.
  - Door Unlocked (Exit Button)
  - Door Unlocked (By Operator)
3. Added relay deactivation option for exit button input.
  - Added the option to set the door open request log to occur but the relay not to operate when the exit button is pressed.

## Bug Fixes

1. Card types not checked in smart card settings are issued normally (Affects version: v1.5.0).
2. Added code to prevent authentication fail caused by broken database or cache memory (Affects version: v1.0.0).

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge./doku.php?id=en:bew2\\_revision\\_note\\_171&rev=1674779009](http://kb.supremainc.com/knowledge./doku.php?id=en:bew2_revision_note_171&rev=1674779009)

Last update: **2023/01/27 09:23**