

Table of Contents

| | |
|-------------------------------------|---|
| Version 1.7.1 (V1.7.1_221220) | 1 |
| Release | 1 |
| New features and improvements | 1 |
| Bug Fixes | 1 |

Version 1.7.1 (V1.7.1_221220)

Release

2023-01-11

Devices with the new SE processor cannot downgrade to a lower version after upgrading the firmware to v1.7.1 or higher.
Devices with existing SE processor can be downgraded to a lower version.
For more information, check the serial number of the device and contact the Suprema.
(supremainc.com)

New features and improvements

1. Supports a new SE processor and new firmware.
2. Separated the log related to the cause of the door unlock.
 - Door open request by exit button
 - Door open request by operator
3. Added relay deactivation option for exit button input.
 - Added the option to set the door open request log to occur but the relay not to operate when the exit button is pressed.

Bug Fixes

1. Card types not checked to be used in smart card settings gets issued normally (Affects version: v1.5.0).
2. Improved the structure to prevent authentication fail caused by broken database or cache memory (Affects version: v1.0.0).

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge./doku.php?id=en:bew2_revision_note_171&rev=1698729109

Last update: **2023/10/31 14:11**