

Table of Contents

Version 1.1.0 (V1.1.0_240104)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.1.0 (V1.1.0_240104)

Release

2024-01-04

New Features and Improvements

1. Supports **Custom Smart Card Layout**.
2. Applied Open SSL 3.0.10.
 - After upgrading the firmware to v1.1.0, it is not able to downgrade to an earlier version of the firmware.
3. Extended the user expiration period to a maximum of '**2037-12-31**'.
4. Improved pop-up message to be displayed when **Timed Anti PassBack** occurs.
5. Improved **Key Menu** screen UI.

Bug Fixes

1. When **Relay** is set in the device menu, the door does not open with a mobile card. (Affects version: v1.0.0)
2. The device abnormally restarts when changing the device's Network settings in BioStar 2. (Affects version: v1.0.0)
3. Cannot connect to a wireless network by manually entering the SSID in **Wireless LAN**. (Affects version: v1.0.0)
4. Authentication fails when authenticating with a DESFire AoC while the device is connected as a slave. (Affects version: v1.0.0)
5. When authenticating with ID + PIN on a device connected as a slave, the user ID is displayed but the user name is not displayed. (Affects version: v1.0.0)
6. The device restarts when formatting and reissuing the user's iClass AoC in BioStar 2. (Affects

version: v1.0.0)

7. When pressing the OK button consecutively and then pressing the directional key, a beep sound plays, resulting in an authentication failure. (Affects version: v1.0.0)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bs2a_revision_note_110

Last update: **2024/01/15 11:31**