

Table of Contents

Version 1.0.0 (V1.0.0_160205)	1
Release	1
Bug fixes	1
Version 1.0.0 (V1.0.0_151223)	1
Release	1

Version 1.0.0 (V1.0.0_160205)

Release

2016-02-05

Bug fixes

1. Issue with door relay operation.
2. Issue with alarm lasting time.

Version 1.0.0 (V1.0.0_151223)

Release

2015-12-23

1. Initial firmware developed.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bsa2_revision_note_100

Last update: **2021/05/13 15:00**