

Table of Contents

Version 1.6.1 (V1.6.1_190405)	1
Release	1
Bug fix	1

Version 1.6.1 (V1.6.1_190405)

Release

2019-04-10

Bug fix

1. The device's touch screen operates abnormally due to interference at a frequency of 125 kHz.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bsa2_revision_note_161

Last update: **2021/05/13 11:03**