

Table of Contents

| | |
|-------------------------------------|---|
| Version 1.0.2 (V1.0.2_160602) | 1 |
| Release | 1 |
| Bug fixes | 1 |

Version 1.0.2 (V1.0.2_160602)

Release

2016-06-02

Bug fixes

1. Issue where the device does not boot if the OP5 sensor isn't assembled.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bsl2_revision_note_102

Last update: **2021/05/17 17:00**