

# Table of Contents

Firmware Version 1.0.1 (Build No. 1.0.1\_250625) ..... 1

Release ..... 1

Bug Fixes ..... 1

# Firmware Version 1.0.1 (Build No. 1.0.1\_250625)

## Release

2025-06-26

## Bug Fixes

1. The door relay operates abnormally when the connection to the master device is lost. (Affects version: v1.0.0)
2. When a specific device is connected as a slave, configuration changes are not properly applied. (Affects version: v1.0.0)
3. Slave devices are intermittently not detected or get disconnected. (Affects version: v1.0.0)
4. The **Custom Smart Card Layout** set on the slave device is not displayed properly on the device detail page. (Affects version: v1.0.0)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge./doku.php?id=en:di-24\\_revision\\_note\\_101](http://kb.supremainc.com/knowledge./doku.php?id=en:di-24_revision_note_101)

Last update: **2025/07/09 10:04**