

Table of Contents

Version 1.0.4 (V1.0.4_180116)	1
Release	1
New Features and Improvements	1

Version 1.0.4 (V1.0.4_180116)

Release

2018-01-17

New Features and Improvements

1. Changed the Touch IC firmware and the kernel changed by firmware difference.
2. Adjusts the camera calibration offset due to Window PET film changes.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:fs2_revision_note_104

Last update: **2021/05/12 10:26**