

Table of Contents

Version 1.4.1 (V1.4.1_210203)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.4.1 (V1.4.1_210203)

Release

2021-02-16

New Features and Improvements

1. Suprema Thermal Camera (TCM10-FS2) SDK Revision

- FPS 8.3 applied
- The management service is separated to recover the system safely after the device stops working abnormally.
- The infrared image motion stopped working or the device was restarted while using the thermal camera.
- The specifications of captured image buffer were modified.

2. Renamed the thermal camera's feature (English only)

- Before: Emission Rate
- After: Emissivity

Bug Fixes

1. Disconnected logs frequently occurred when the device was used with Secure I/O 2. (Affects version: v.1.4.0 or earlier)

2. Doors were not applied in the open state when the device was restarted with the door set to manual open mode. (Affects version: v.1.4.0)

3. The Secure Tamper could not be manually turned off by the default hash key. (Affects version: v.1.4.0)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:fs2_revision_note_141&rev=1620777138

Last update: **2021/05/12 08:52**