

# Table of Contents

Version 1.1.8 (V1.1.8_160119) .....	1
Release .....	1
Bug fixes .....	1

## Version 1.1.8 (V1.1.8\_160119)

### Release

2016-01-19

### Bug fixes

1. OSDP ID is changed to zero and communication is not possible if FW upgrade is performed when connecting to BioStation 2 or BioStation A2 as a slave device.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:sio2\\_revision\\_note\\_117&rev=1621297890](http://kb.supremainc.com/knowledge/doku.php?id=en:sio2_revision_note_117&rev=1621297890)

Last update: **2021/05/18 09:31**