

# Table of Contents

Version 1.7.2 (V1.7.2_231102) .....	1
Release .....	1
Bug Fixes .....	1

## Version 1.7.2 (V1.7.2\_231102)

### Release

2023-11-03

Devices with the new BLE chip cannot downgrade to a lower version after upgrading the firmware to v1.7.0 or higher. Devices with existing BLE chips can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema. (<https://supremainc.com>)

### Bug Fixes

1. When running the Device Manager application v1.1.8 on iOS, certain devices do not connect. (Affects version: v1.7.0)
2. Custom smart card byte order is affected by the CSN card byte order setting. (Affects version: v1.7.1)
3. In the Device Manager application, there is an issue where the default **Encryption Type** is set to 'DES/3DES' instead of 'AES' when configuring a **DESFire** card in the **Suprema Smart Card Layout** tab. (Affects version: v1.0.0)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge./doku.php?id=en:xpd2\\_rev2\\_revision\\_note\\_172](https://kb.supremainc.com/knowledge./doku.php?id=en:xpd2_rev2_revision_note_172)

Last update: **2024/10/22 17:06**