

# Table of Contents

1.0.2 Version (V1.0.2_210614) .....	1
Release .....	1
Bug Fixes .....	1

## 1.0.2 Version (V1.0.2\_210614)

### Release

2021-06-18

### Bug Fixes

1. Micom firmware upgrade failed intermittently. (Affects version: v1.0.1)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

[https://kb.supremainc.com/knowledge/doku.php?id=en:xs2\\_revision\\_note\\_102](https://kb.supremainc.com/knowledge/doku.php?id=en:xs2_revision_note_102)

Last update: **2024/04/11 13:16**