

# Table of Contents

1.0.2 Version (V1.0.2_210614) .....	1
Release .....	1
Bug fixes .....	1

## 1.0.2 Version (V1.0.2\_210614)

### Release

2021-06-18

### Bug fixes

1. Micom firmware upgrade failed intermittently. (Affects version: v1.0.1)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:xs2\\_revision\\_note\\_102&rev=1624344176](http://kb.supremainc.com/knowledge/doku.php?id=en:xs2_revision_note_102&rev=1624344176)

Last update: **2021/06/22 15:42**