

# Table of Contents

Version 1.4.4 (V1.4.4\_220914) ..... 1

Release ..... 1

New features and improvements ..... 1

Bug Fixes ..... 1

# Version 1.4.4 (V1.4.4\_220914)

## Release

2022-09-14

- BEP2-OA type of BioEntry P2 model support HID iCLASS card type through SE processor. For devices with the new SE processor, after upgrading the firmware to v1.4.4 or higher, you cannot downgrade to a lower version and downgrade the firmware customized in the lower version. Devices with existing SE processor can be downgraded to a lower version.
- For more information, check the serial number of the device and contact the Suprema. (supremainc.com)

## New features and improvements

1. Supports the dual SE processor.

## Bug Fixes

1. Incorrect Bit Count and card data were output when the Suprema device was connected to a 3rd-party controller via OSDP and the CSN card was registered in Wiegand format and authenticated. (Affects version: v1.4.3)
2. Device does not recognize certain HID iCLASS Seos cards. (Affects version: v1.0.0)
3. Event logs and real-time logs are not output due to corrupted log records. (Affects version: v1.0.0)
4. Improved the structure to prevent authentication fail caused by broken database or cache memory. (Affects version: v1.0.0)

From:  
<http://kb.supremainc.com/knowledge/> -

Permanent link:  
[http://kb.supremainc.com/knowledge/doku.php?id=en:bep2\\_revision\\_note\\_144](http://kb.supremainc.com/knowledge/doku.php?id=en:bep2_revision_note_144)

Last update: **2023/11/27 11:51**