

Table of Contents

Version 1.1.1 (V1.1.1_180720) 1

 Release 1

 Bug Fixes 1

Version 1.1.1 (V1.1.1_180720)

Release

2018-07-25

Bug Fixes

1. The device restarts when authentication fails.
2. The RF module of the device gets damaged when using a 13.56 MHz card.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:ber2_revision_note_111

Last update: **2021/06/01 13:12**