

Table of Contents

Version 1.0.1 (V1.0.1_160921) 1

 Release 1

 Bug Fixes 1

Version 1.0.1 (V1.0.1_160921)

Release

2016-09-22

Bug Fixes

1. Memory leak issue when a T&A device is registered as a slave device and users authenticate after pressing a T&A key.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_101

Last update: **2021/05/28 12:23**