

Table of Contents

Version 1.3.1 (V1.3.1_190228) 1

Release 1

Bug Fixes 1

Version 1.3.1 (V1.3.1_190228)

Release

2019-03-12

Bug Fixes

1. The device intermittently recognizes the HID Prox card as an EM card.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_131

Last update: **2021/05/31 08:36**