

Table of Contents

Version 1.4.1 (V1.4.1_190911) 1

Release 1

Bug Fixes 1

Version 1.4.1 (V1.4.1_190911)

Release

2019-09-18

Bug Fixes

1. After a user scans and registers a card on a device set as Wiegand Out device, if an existing user authenticates with a credential other than the card, the Wiegand output will behave abnormally.
2. The device restarts if a user authenticates a fingerprint on the device set as below.
 - Byte Order: LSB
 - Wiegand Out: User ID
3. When using firmware V1.4.0 the connection to the I/O device that using the firmware version below is lost.
 - DM-20 FW V1.1.2
 - OM-120 FW V1.0.0
 - Secure I/O 2 FW V1.2.1
4. The master device intermittently reboots when upgrading the firmware of the slave device.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_141

Last update: **2021/05/28 10:59**