

Table of Contents

Version 1.5.0 (V1.5.0_200722) 1

Release 1

New Features and Improvements 1

Bug Fixes 1

Version 1.5.0 (V1.5.0_200722)

Release

2020-07-22

New Features and Improvements

1. Added feature to change device ID.
2. Enhancement in the security of the device.
 - Restrict unencrypted connections.
 - Enhancement in the security of encryption keys.
 - Encrypt and migrate user information.
3. Improved Anti-passback zone to operate based on the door status.
4. Improved the scheduled unlock zone function for each floor when controlling elevator.
5. Supports new device.
 - XPass D2 (Rev 2)
6. Changed the color of LED indicator.

Bug Fixes

1. Improved the device to recognize unknown cards by selecting the card type options. (BEW2-OAP)
2. OSDP Communication does not work normally if the value sent to the slave device is greater than the defined value.
3. Device reboots or a timeout occurs when upgrading firmware or transferring user data during SSL secure communication.
4. The event log of the device is not sent in the order in which it occurred.
5. Issue that the option for card types is deactivated when the device is connected as a slave after the factory reset.
6. Issue that the connection of the slave device is disconnected when the slave device is connected.
7. Device reboots when there is no operation after connecting power.
8. Device shows low reading performance with low frequency cards even when card is placed within an operating distance.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_150

Last update: **2021/05/28 10:56**