

Table of Contents

Version 1.6.2 (V1.6.2_201202) 1

Release 1

Bug Fixes 1

Version 1.6.2 (V1.6.2_201202)

Release

2020-12-02

Bug Fixes

1. After the firmware of both a master device and a slave device was upgraded to the version 1.6.x., the reconnection between devices failed when rebooting the slave device. (BEW2-OAP, BEW2-OHP, BEW2-ODP)
2. Delay occurred intermittently when reading a FeliCa card. (BEW2-OAPB, BEW2-OHPB, BEW2-ODPB)

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:bew2_revision_note_162

Last update: **2021/05/28 10:48**