

Table of Contents

Version 1.0.2 (V1.0.2_160602) 1

Release 1

Bug fixes 1

Version 1.0.2 (V1.0.2_160602)

Release

2016-06-02

Bug fixes

1. Issue where the device does not boot if the OP5 sensor isn't assembled.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bsl2_revision_note_102

Last update: **2021/05/17 17:00**