

# Table of Contents

Version 1.3.1 (V1.3.1\_200422) ..... 1

Release ..... 1

Bug Fixes ..... 1

## Version 1.3.1 (V1.3.1\_200422)

### Release

2020-04-27

### Bug Fixes

1. Changed the firmware downgrade policy.
  - The kernel of the firmware before the touch panel is replaced has been changed not to downgrade.
2. Adjusted the brightness of the IR LED.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:fs2\\_revision\\_note\\_131](http://kb.supremainc.com/knowledge/doku.php?id=en:fs2_revision_note_131)

Last update: **2021/05/12 09:28**