

Table of Contents

1.0.5 Version (V1.0.5_210422) 1

Release 1

Bug Fixes 1

1.0.5 Version (V1.0.5_210422)

Release

2021-05-06

Bug Fixes

1. An infrared image was not displayed when connecting the device to the thermal camera.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:fsf2_revision_note_105

Last update: **2021/05/11 10:39**