

Table of Contents

Version 2.9.5 (V2.9.5.29)

Release

New Features and Improvements

Bug Fixes

1

1

1

2

Version 2.9.5 (V2.9.5.29)

Release

2024-03-18

Notice on improved Administrator Guide

Starting with BioStar v2.9.5, **Feature Guide** is provided separately by topic on how to use new or improved features.

New Features and Improvements

1. Added **New Dashboard** feature.
2. Added **Quick Action** feature.
3. Added **Timed Anti PassBack** feature in the **DOOR** menu.
4. Supports user profile photo and visual face enrollment using webcam.
5. Improved **USER** menu.
 - Added column types that can be displayed on the **USER** menu screen.
Period (**Start datetime**, **End datetime**), **Operator Level**, **Login ID**, **User IP**, **PIN**, **QR/Barcode**, **Mobile Access Card**
 - Added **Advanced Search** feature.
ID, **Name**, **Email**, **Department**, **Title**, **Telephone**, **Group**, **Access Group**, **Status**, **Operator Level**, **Card**, **Custom User Field**
6. Improved **TRIGGER & ACTION** menu.
 - Added events displayed in **MONITORING**.
 - Supports door relay operation settings.
 - Added notification email sending function based on action.
 - Added **Action List** where multiple actions can be set as one.
7. Improvements have been made to allow setting **Suprema Smart Card** from **Batch Edit**.
8. Added **CSV Field** to prevent already issued **Template on Mobile** from being deleted when overwritten by **CSV Import**.
 - ToM AoC, ToM SCC
9. Changed CoreStation's wireless antenna module and wireless door lock connection specification

- Wireless antenna modules that can be connected to one CoreStation: 1 → 2
- Wireless door locks that can be connected to one wireless antenna module: 8 → 6
- Maximum connectable wireless door lock: 8 → 12

10. Improved certificate errors due to Google Chrome and Microsoft Edge browser updates.

Bug Fixes

1. **REPORT** menu is not available when using a separate domain and private certificate. (Affects version: v2.9.3)
2. **REPORT** menu is not available when installed on an Azure database. (Affects version: v2.9.3)
3. When printing Unicode characters on cards using **Card Printer**, the characters are printed garbled. (Affects version: v2.9.3)
4. The operation fails if it takes more than 1 minute when using **Unified Gateway**. (Affects version: v2.9.3)
5. In an environment where multiple OM-120s are connected to the master device and the device is synchronized using the **Automatic User Synchronization - Specific Devices** mode and then authenticated, the relay malfunctions. (Affects version: v2.7.14)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:release_note_295

Last update: **2024/03/26 16:11**