

# Table of Contents

Version 1.7.0 (V1.7.0\_220921) ..... 1

Release ..... 1

New Features and Improvements ..... 1

Bug Fixes ..... 1

# Version 1.7.0 (V1.7.0\_220921)

## Release

2022-09-21

Devices with the new BLE chip cannot downgrade to a lower version after upgrading the firmware to v1.7.0 or higher. Devices with existing BLE chips can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema. (supremainc.com)

## New Features and Improvements

1. Supports a new BLE (Bluetooth Low Energy) chip.
  - The BLE chip parts of the hardware have been changed, and the firmware has been upgraded to be compatible with both the existing and new BLE chips.
2. Improved setting of the byte order for smart cards.
  - Improved to display valid values through Wiegand or OSDP when the AoC (Access on Card) ID issued by BioStar 2 is set to Alphanumeric.

## Bug Fixes

1. Intermittent Mobile Card not authenticating (Affects version: v1.4.0).
  - Improved BLE Micom Firmware and BLE Recovery RfCore.
2. When FaceStation F2 and Xpass D2 are connected as master-slave, Xpass D2 cannot authenticate with Mobile Card (Affects version: v1.4.0).

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

[http://kb.supremainc.com/knowledge/doku.php?id=en:xpd2\\_rev2\\_revision\\_note\\_170](http://kb.supremainc.com/knowledge/doku.php?id=en:xpd2_rev2_revision_note_170)

Last update: **2023/11/27 14:48**