

Table of Contents

Version 1.0.2 (V1.0.2_180702)

Release

New Features and Improvements

Bug fixes

Version 1.0.2 (V1.0.2_180702)

Release

New Features and Improvements

1

1

1

1

1

1

1

Version 1.0.2 (V1.0.2_180702)

Release

2018-07-25
XPass D2-MDB

New Features and Improvements

1. Improves the performance of RS-485 communication.

Bug fixes

1. The device LED displays in the wrong color if the door is opened when the intrusion alarm zone is set to Arm.
2. The device does not stop playing the Arm/Disarm Delay Time alarm sound if restarting the master device while the alarm sound is playing in the intrusion alarm zone.
3. The device LED displays in the wrong color if pressing the reset button more than 5 times when setting the RS-485 rate.
4. The device plays the card scan sound for 10 seconds when authenticating with the mobile card.
5. The device LED displays in the wrong color if authenticating by AoC with the unsupported Auth Mode when connected as a slave to a 3rd-party device.

Version 1.0.2 (V1.0.2_180702)

Release

2018-07-27
XPass D2-GDB, XPass D2-GKDB

New Features and Improvements

1. Add XPass D2(XPD2-GKDB).

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:xpd2_revision_note_102

Last update: **2021/05/31 09:45**