

Table of Contents

Version 1.2.2 (V1.2.2_230602) 1

Release 1

Bug Fixes 1

Version 1.2.2 (V1.2.2_230602)

Release

2023-06-08

XS2-APB, XS2-QAPB and XS2-OAPB types of X-Station 2 model support HID iClass card type through SE processor.

For devices with the new SE processor, after upgrading the firmware to v1.1.4 or higher, you cannot downgrade to a lower version and downgrade the firmware customized in the lower version.

Devices with existing SE processor can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema. (supremainc.com)

Bug Fixes

1. Device abnormally restarts when **Image Log** is **Enabled** and image log is logged on the device. (Affects version: v1.2.0)
2. When authenticating with a BLE mobile card running on iOS, authentication fails and the device restarts intermittently. (Affects version: v1.0.0)

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:xs2_revision_note_122

Last update: **2023/10/04 10:45**