Table of Contents

/ersion 1.3.0 (V1.3.0_240318)	1
Release	1
New Features and Improvements	
Bug Fixes	2

Version 1.3.0 (V1.3.0_240318)

Release

2024-03-26

XS2-APB, XS2-QAPB and XS2-OAPB types of X-Station 2 model support HID iClass card type through SE processor.

For devices with the new SE processor, after upgrading the firmware to v1.1.4 or higher, you cannot downgrade to a lower version and downgrade the firmware customized in the lower version.

Devices with existing SE processor can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema. (supremainc.com)

New Features and Improvements

- 1. Extended the user expiration period to a maximum of '2037-12-31'.
- 2. Supports Custom Smart Card Layout.
- 3. Supports the **Display Result from Controller** feature for displaying authentication success or failure results from a 3rd party controller on the device screen when using **Intelligent Slave**.
- 4. XPass D2 new BLE (Bluetooth Low Energy) chip firmware (Build No. 1.7.0 220921) support.
- The BLE chip parts of the hardware have been changed, and the firmware has been upgraded to be compatible with both the existing and new BLE chips.
- 5. Supports the **Ignore Repeated Signals Duration** feature, which ignores repetitive authentication signals from the controller when the device is connected to a 3rd party controller via Wiegand.
- 6. **Face Detection** feature is deprecated.
- 7. Added event code for OR authentication.
- 8. Improved synchronization to complete if user enrollment fails when synchronizing multiple users to the device in BioStar 2.

- 9. Improved duplicate fingerprint detection.
- 10. Improved pop-up message displayed when moving to another screen after entering the license menu.

Bug Fixes

- 1. The device fails to connect via OSDP with the 3rd party control panel. (Affects version: v1.1.0)
- 2. When authenticating while **SmartCard Byte Order** is set to **LSB**, the smart card ID outputs incorrect values, and the device restarts abnormally. (Affects version: v1.2.0)
- 3. Device does not recognize certain MIFARE Classic cards. (Affects version: v1.0.0)
- 4. When authenticating with the QR Code issued to the user while **Use QR as Card** is activated, incorrect BitCount and CardData get transferred via OSDP. (Affects version: v1.2.0)
- 5. Authentication fails when authenticating with a DESFire AoC while the device is connected as a slave. (Affects version: v1.0.0)
- 6. When **Relay** is set in the device menu, the door does not open with a mobile card. (Affects version: v1.0.0)
- 7. The user ID stored as a 32-character string is truncated to only 31 characters in a specific event log. (Affects version: v1.0.0)
- 8. When authenticating in **T&A Mode** with **Server Private Msg.** or **Device Private Msg.** enabled, the set private message is displayed incorrectly. (Affects version: v1.0.0)
- 9. Event logs occurred while the LAN cable was disconnected from the device are not updated to BioStar 2 after reconnecting the LAN cable. (Affects version: v1.0.0)
- 10. The camera of the device authenticates QR codes even while the device is locked. (Affects version: v1.2.0)
- 11. If the number of fingerprints stored in the device exceeds the 1:N maximum, the **Finger** in **User Usage** count is displayed abnormally. (Affects version: v1.2.0)

From:

http://kb.supremainc.com/knowledge/ -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:xs2_revision_note_130

Last update: 2024/04/11 13:14