

Table of Contents

Version 1.3.1 (V1.3.1_190911)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

Version 1.3.1 (V1.3.1_190911)

Release

2019-09-19

New Features and Improvements

1. Improved the speed at which the device recognizes 13.56 MHz cards.

Bug Fixes

1. The device recognizes the DESFire(Adv) card as a CSN if the device is restarted when the smart card layout set as DESFire(Adv).
2. When using firmware V1.3.0 the connection to the I/O device that using the firmware version below is lost.
 - DM-20 FW V1.1.2
 - OM-120 FW V1.0.0
 - Secure I/O 2 FW V1.2.1
3. The device restarts if a user authenticates a fingerprint on the device set as below.
 - Byte Order: LSB
 - Wiegand Out: User ID
4. After a user scans and registers a card on a device set as Wiegand Out device, if an existing user authenticates with a credential other than the card, the Wiegand output will behave abnormally.
5. The master device intermittently reboots when upgrading the firmware of the slave device.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:bep2_revision_note_131

Last update: **2021/06/01 09:19**