

Table of Contents

1.0.3 Version (V1.0.3)	1
Release	1
New Features and Improvements	1
Bug Fixes	1

1.0.3 Version (V1.0.3)

Release

2021-02-02

New Features and Improvements

1. Changes to a new LCD screen

After upgrading a firmware to v1.0.3, you cannot downgrade the firmware to the previous version that includes the kernel and U-Boot.

Bug Fixes

1. When a user authenticated using the iCLASS Seos AoC (Access on Card) after saving a face in it, the device timed out or recognized the AoC as a CSN.
2. Motion detection did not work properly after scanning a card.
3. When using T&A mode, the device did not recognize a card intermittently.

From:

<https://kb.supremainc.com/knowledge/> -

Permanent link:

https://kb.supremainc.com/knowledge/doku.php?id=en:fsf2_revision_note_103&rev=1620696046

Last update: **2021/05/11 10:20**