# **Table of Contents**

1.0.4 Version (V1.0.4)	
Release	
Bug Fixes	

## 1.0.4 Version (V1.0.4)

#### Release

2021-03-10

## **New Features and Improvements**

- 1. Suprema Thermal Camera (TCM10-FSF2) SDK Revision
- FPS 8.3 applied
- The management service is separated to recover the system safely after the device stops working abnormally.
- The infrared image motion stopped working or the device was restarted while using the thermal camera.
- The specifications of captured image buffer were modified.

## **Bug Fixes**

- 1. The firmware version of the thermal camera was not displayed.
- 2. The previous T&A code setting was maintained even after changing the setting.
- 3. A timeout occurred when a user set to Exclude Device Default Authentication Mode attempted to authenticate a card on a slave device with authentication mode set to Card+PIN.
- 4. The thermal camera froze up when updating resources via BioStar 2.
- 5. Improved the Visual Face matching algorithm.
- Improved the face recognition algorithm for users with glasses.
- Improved the authentication performance when wearing masks.

#### From:

https://kb.supremainc.com/knowledge/ -

#### Permanent link:

 $https://kb.supremainc.com/knowledge/doku.php?id=en:fsf2\_revision\_note\_104\&rev=1620696299$ 

Last update: 2021/05/11 10:24