

Table of Contents

1.0.5 Version (V1.0.5)	1
Release	1
Bug Fixes	1

1.0.5 Version (V1.0.5)

Release

2021-05-06

Bug Fixes

1. An infrared image was not displayed when connecting the device to the thermal camera.

From:

<http://kb.supremainc.com/knowledge/> -

Permanent link:

http://kb.supremainc.com/knowledge/doku.php?id=en:fsf2_revision_note_105&rev=1620696414

Last update: **2021/05/11 10:26**